## Regulation 1138 - Section 10 Management practices

- Minimize tank bath agitation when removing any parts
- Maximize the draining of parts upon removal
- Optimize the design of barrels, racks, and parts to minimize drag out
- Use tank covers, if already owned and available
- Minimize or reduce heating of tank baths
- Perform regular repair, maintenance, and preventive maintenance
- Minimize tank bath contamination
- Maintain quality control of chemicals used in tank baths
- Maintain quality control of chemical and other bath ingredient concentrations in the process tanks
- Perform general good housekeeping through regular sweeping or vacuuming and periodic wash downs
- Minimize spills and overflows
- Perform regular inspections to identify leaks and opportunities for pollution prevention
- Use a squeegee system in continuous or reel-to-reel process tanks

All management practices contain the proviso "as practicable"

